

**PATENT**

Attorney Docket No. 27006-0002

**IN THE UNITED STATES PATENT AND TRADEMARK OFFICE**

Patent Number: 7,188,708 B2

Issued: March 13, 2007

Name of Assignee: Petroliam Nasional Berhad

Inventor(s): Azmi B. Osman

Title of Invention: OIL PAN FOR AUTOMOBILE ENGINE

**REQUEST FOR CORRECTED CERTIFICATE OF CORRECTION OF  
PATENT FOR PATENT OFFICE MISTAKE (37 C.F.R. § 1.322(a))**

Commissioner For Patents  
P.O. Box 1450  
Alexandria, Virginia 22313-1450

Attn: Decision and Certificate of Correction  
Branch of the Patent Issue Division

Dear Sir:

It is requested that a corrected Certificate of Correction be issued to correct an error found in the original Certificate of Correction received for the above-identified patent. Applicants attach hereto a marked-up copy of the Certificate of Correction indicating the following error:

Column 1, line 7, "P1 2000 6077" should be --PI 2000 6077--. The "1" in "P1" should be a capital letter I.

Please forward a corrected Certificate to the correspondence address of record.

Respectfully submitted,

DICKINSON WRIGHT PLLC

Date: May 10, 2007

/Richard A. Jones/

Richard A. Jones  
Reg. No. 39,242

1901 L Street N.W.  
Suite 800  
Washington, DC 20036  
(248) 433-7285

RAJ/gmp  
Attachment

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 7,188,708 B2  
APPLICATION NO. : 10/027814  
DATED : March 13, 2007  
INVENTOR(S) : Azmi B. Osman

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:


PI

Column 1, line 7, "P1 2000 6077" should be --~~P1~~ 2000 6077--.

Column 2, lines 29 and 30, "chennels" should be --channels--.

Signed and Sealed this

First Day of May, 2007


JON W. DUDAS  
*Director of the United States Patent and Trademark Office*